brulin™

World Class Cleaning Solutions

Case Study

Custom Motorcycle/Harley Sales & Service

CUSTOMER DETAILS

Product: AquaVantage[®] 815 GD
Parts Cleaned: Chrome parts, engine parts, carburetors
Removing What: Carbon, old gas , corrosion
Scenario: Service/repair...online used parts business
Equipment: Omegasonics Pro Plus Model 5028-33Gal

CUSTOMER'S CURRENT PROCESS:

Current Chemistry: AquaVantage® 815 GD Concentration: 6-8% Washer Type: 33 Gallon Omegasonics Pro Plus Specific Metals: Crome plated, steel Temperature: 160°F (71.1°C) Time: 5 min Rinse Water Temp: 160°F (71.1°C) Rinse Water Number and Time: 1 for 5 min Dry: 150°F (65.6°C) for 5 minutes Tank Life: Measured in days Customer Improvement Requested: None at this time

CURRENT SITUATION WITH PROCESS

Customer has a large online used parts business..cleaning with 815 GD makes the parts look brand new which increases value to their customers.

