



World Class Cleaning Solutions

Case Study

Turbine Blade Facility: FPI Prep.

CUSTOMER DETAILS

- Product:** AquaVantage® 815 GD
- Parts Cleaned:** Turbine Blades
- Removing What Soil(s):** Coolants and Lubricants
- Primary Problem:** Poor Tank Maintenance
- Why are Parts Degreased:** Inspection & Repair of turbine blades, prep for FPI
- Washing System:** OMEGASONICS 33 gallon

BRULIN IMPLEMENTED PROCESS

Recommendation for tank de-scaling: drain tanks, descale with Brulin De-Scaler at 25% X 30 minutes followed by freshwater rinse. Charge cleaned system as follows, begin regular tank maintenance with tank titration at least weekly.

- Total Wash Tank Volume:** 33 Gallon
- Concentration:** 10%
- Wash Temperature:** 145°F (63°C)
- Clean Time:** 10 Minutes
- Rinse Temperature:** Ambient
- Rinse Time:** 1 Minute, manual

RESULTS

Foul odor removed, tank life extended, cleaner parts

