

# World Class Cleaning Solutions

# **Case Study**

Manufacturer of Critical Performance Products: TCE Replacement

### **CUSTOMER DETAILS**

Product: AquaVantage® 1990 GD

Parts Cleaned: Aluminum, for aerospace industry. Removing What Soil(s): Cutting oils, dirt, grease

Why are Parts Degreased: Cleaning required prior to the next stage in the manufacturing process.

# **CUSTOMER PROCESS BRULIN REPLACED**

Current Chemistry: TCE
Concentration: Unknown
Washer Type: Ultrasonic Washer
Specific Metals: Aluminum
Temperature: Unknown
Time/Line Speed: Unknown

Customer Improvement Requested: Owner wants TCE out of facility

## **BRULIN IMPLEMENTED PROCESS**

Chemistry: AquaVantage® 1990 GD

Concentration: 5% Temperature: 150°F (66°C) Time/Line Speed: 5 minutes

#### **REASON BRULIN WON**

This was a joint project with Almco, parts washer manufacturer. They are 45 minutes from the customer. We were able to have people from the customer come down to Almco to test AquaVantage® 1990 GD in their spray washer.

