



# World Class Cleaning Solutions

## Case Study

### Aerospace MRO

#### CUSTOMER DETAILS

**Product:** AquaVantage® 3887 GD  
**Parts Cleaned:** GE Fuel Pump Housing  
**Removing What Soil(s):** Dirt, Grease, Oil, and burnt on carbon  
**Why are Parts Degreased:** They require critically clean parts

#### CUSTOMER PROCESS BRULIN REPLACED

**Current Chemistry:** Stoddard  
**Washer Type:** Hand Brushed  
**Customer Improvement Requested:** Automated and Quicker clean time

#### BRULIN IMPLEMENTED PROCESS

**Chemistry:** AquaVantage® 3887 GD  
**Concentration:** 7.5%  
**Temperature:** 145°F  
**Time/Line Speed:** 20 Minutes  
**Dry:** Not required

#### RESULTS

Critically cleaned components.

#### REASON BRULIN WON

We have a good relationship with this customer and they are very happy with this product.