



# World Class Cleaning Solutions

## Case Study

### Medical Tubing Manufacturer

#### CUSTOMER DETAILS

**Parts Cleaned:** Vascular and Non-Vascular Tubing  
**Specific Substrates:** PTFE  
**Removing What Soil(s):** Light silicone film from outer surface used as a process lubricant  
**Why are Parts Degreased:** Preparation for additional part processing, not a final clean

#### CUSTOMER'S BRULIN PROCESS

**Chemistry:** AquaVantage® 815 GD  
**Concentration:** 7-10%  
**Washer Type:** Custom Inline ultrasonic bath line  
**Temperature:** 149°F (65°C)  
**Customer Improvement Requested:** Removal of silicone residue from outer surface.

